and U-shaped metal fitting 12. 13 is a boss part, and 14 is a spoke.

Fig. 1





Fig. 2



APPENDUX 5 PAGE 1 OF 2




Fig. 4





Fig. 5



8

